


12.3.8v.6  
NO DATE

**DRAFT**

**LEGEND AND NOTES**

⊙ Monitoring Well  
 ⊕ Product Recovery Sump  
 1. Plan view is based on labeled measurements in the field and should be considered approximate. Field verify prior to excavation.  
 --- Approximate limits of soil Excavation, October 1992  
 ⊗ Spot Elevation



**NORTH**

0 5 10  
Scale in Feet

**FIGURE 2**  
 Site Map  
 LONGVIEW FIBRE COMPANY  
 SEATTLE, WASHINGTON

**USEPA SF**  
  
 1256924

LFC003519 bl